

Elbow Kit Instructions

To use with HUG Hydronics







Your elbow kit contains:

- 2) PVC elbows
- 2) PVC conduit clamps
- 4) screws

The elbow kit is designed to hold and control PEX piping for your in-floor hydronic heat system. Each kit will handle 1 loop of PEX piping.

Step 3



- 1. The elbows are the beginning and end of each PEX loop.
- 2. Place them where you want your PEX hose to come in and out of the floor.
- 3. Screw them into place by with conduit clamps (as pictured on the left).

4. Start each PEX loop by running it through an elbow. Staple or zip tie your loop into place according to your plans. End the Pex loop by running it through the elbow next to the starting loop

